



Переход Т-образный плавный ПТп



Артикул	Номер для заказа		Ширина (B1) мм	Ширина (B2) мм	Длина (L1) мм	Длина (L2) мм	Высота (H) мм	Вес кг/шт	Упаковка шт
	ZS	RAL							
ПТп 100x50x50	034415	234415	100	50	350	250	50	0,53	2
ПТп 200x50x50	034425	234425	200	50	350	350	50	0,73	2
ПТп 300x50x50	034435	234435	300	50	350	450	50	0,92	2
ПТп 400x50x50	034445	234445	400	50	350	550	50	1,11	2
ПТп 50x100x50	034451	234451	50	100	400	200	50	0,51	2
ПТп 200x100x50	034421	234421	200	100	400	350	50	0,84	2
ПТп 300x100x50	034431	234431	300	100	400	450	50	1,06	2
ПТп 400x100x50	034441	234441	400	100	400	550	50	1,28	2
ПТп 50x200x50	034452	234452	50	200	500	200	50	0,65	2
ПТп 100x200x50	034412	234412	100	200	500	250	50	0,79	2
ПТп 300x200x50	034432	234432	300	200	500	350	50	1,34	2
ПТп 400x200x50	034442	234442	400	200	500	450	50	1,61	2
ПТп 50x300x50	034453	234453	50	300	600	200	50	0,79	2
ПТп 100x300x50	034413	234413	100	300	600	250	50	0,95	2
ПТп 200x300x50	034423	234423	200	300	600	350	50	1,28	2
ПТп 400x300x50	034443	234443	400	300	600	450	50	1,94	2
ПТп 50x400x50	034454	234454	50	400	700	200	50	0,93	2
ПТп 100x400x50	034414	234414	100	400	700	250	50	1,12	2
ПТп 200x400x50	034424	234424	200	400	700	350	50	1,51	2
ПТп 300x400x50	034434	234434	300	400	700	450	50	1,89	2
ПТп 200x100x80	034521	234521	200	100	400	350	80	1,01	2
ПТп 300x100x80	034531	234531	300	100	400	450	80	1,27	2
ПТп 400x100x80	034541	234541	400	100	400	550	80	1,54	2
ПТп 100x200x80	034512	234512	100	200	500	250	80	0,95	2
ПТп 300x200x80	034532	234532	300	200	500	350	80	1,61	2
ПТп 400x200x80	034542	234542	400	200	500	450	80	1,93	2
ПТп 100x300x80	034513	234513	100	300	600	250	80	1,14	2
ПТп 200x300x80	034523	234523	200	300	600	350	80	1,54	2
ПТп 400x300x80	034543	234543	400	300	600	450	80	2,33	2
ПТп 100x400x80	034514	234514	100	400	700	250	80	1,34	2
ПТп 200x400x80	034524	234524	200	400	700	350	80	1,81	2
ПТп 300x400x80	034534	234534	300	400	700	450	80	2,27	2
ПТп 200x100x100	034621	234621	200	100	400	350	100	1,12	2
ПТп 300x100x100	034631	234631	300	100	400	450	100	1,41	2
ПТп 400x100x100	034641	234641	400	100	400	550	100	1,70	2
ПТп 100x200x100	034612	234612	100	200	500	250	100	1,05	2
ПТп 300x200x100	034632	234632	300	200	500	350	100	1,78	2
ПТп 400x200x100	034642	234642	400	200	500	450	100	2,14	2
ПТп 100x300x100	034613	234613	100	300	600	250	100	1,26	2